


38XPC123D-C
Exploded View Parts for Model



No.		Part Name	Quantity	BOM code	Price	Remark
2		Rear net	1	2011376G0001		
3		Condenser assembly	1	201537490036		
5		Valve plate	1	201237300285		
6		Chassis assembly	1	201237490042		
7		Big handle	1	201137590015		
8		Water collector	1	201137390017		
9		Rear right clapboard assembly	1	201237390082		
10		Partition board assembly	1	201237490025		
11		Front panel	1	201237400389		
12		Air outlet grille	1	201237390105		
13		Reactance	1	202301000847		R8525L (AL)
15		Supporter assembly of fan motor	1	201237400048		
16		Axial flow fan	1	201100320625		
17		Left supporter	1	201237400397		
18		Asynchronous motor	1	202400401345		
20		Top cover assembly	1	201237400398		
21		Electronic control box assembly	1	203337390202		
21.1		Electronic control box	1	201137490028		
21.4		Main control board assembly	1	201337390154		
21.4.1		capacitor	1	202401100992		6UF/250VAC-P0
21.4.1		capacitor	1	202401200152		2. 5uF/450V (BP)
21.10		Radiator	1	202301901137		
22		liquid valve assembly	1	201637591185		
22.1		Liquid valve	1	201600700078		
23		Gas valve assembly	1	201637591187		
23.1		Gas valve	1	201600720194		
25		Compressor	1	201400620600		
38		Supporter of fan motor holder	1	201237400055		
39		Clamp of front net	6	201135110801		
44		Terminal board assembly	1	203337490045		
44.1		Wire joint	1	202301400015		
44.2		Wire clamp	1	201219900001		
44.3		Terminal board	1	201237490039		
45		Cover of electronic control box	1	201137490029		
46		Temperature sensor assembly	1	202301300602		