


38XPQ123D-C

Exploded View Parts for Model



No.		Part Name	Quantity	BOM code	Price	Remark
2		Rear net	1	201137300179		
3		Condenser assembly	1	201537490058		
5		Valve plate	1	201237300286		
6		Chassis assembly	1	201237200262		
8		Water collector	1	201237300295		
9		Rear right clapboard assembly	1	201237300291		
10		Partition board assembly	1	201237300200		
11		Front panel	1	201237300279		
12		Air outlet grille	1	201137300182		
13		Reactance	1	202301000847		R8525L (AL)
15		Supporter assembly of fan motor	1	201237300253		
16		Axial flow fan	1	201100300521		
17		Left supporter	1	201237300281		
18		Asynchronous motor	1	202400401015		
20		Top cover assembly	1	201237300280		
21		Electronic control box assembly	1	203337390211		
21.1		Electronic control box	1	201137490028		
21.4		Main control board assembly	1	201337390164		
21.4.1		capacitor	1	202401100992		6UF/250VAC-P0
21.4.1		capacitor	1	202401200152		2. 5uF/450V (BP)
21.10		Radiator	1	202301901117		
22		liquid valve assembly	1	201637490525		
22.1		Liquid valve	1	201600740703		
23		4-Ways valve assembly	1	201637591220		
23.1		Gas valve	1	201600720701		
23.2		4-Ways valve	1	201600690010		
25		Compressor	1	201400601230		
40		Installation plate of electric parts	1	201237300197		
41		Wire joint	1	202301400015		
42		Insulation plate	1	201137300185		
45		Cover of electronic control box	1	201137490029		
46		Temperature sensor assembly	1	202301300602		